



FL Mining Emergency Information

Four Corners			
Location	Order	Communication Officer	Telephone Number
Plant	Primary	IOC	813-500-6685
	Alternate 1	Flot Plant Operator	863-428-4465
	Alternate 2	Washer Operator	863-428-3495
Field	Primary	IOC	813-500-6685
	Alternate 1	Flot Plant Operator	863-428-4465
	Alternate 2	Washer Operator	863-428-3495
Wingate			
Plant	Primary	IOC	813-500-6685
	Alternate 1	Flot Plant Operator	941-322-6838
	Alternate 2	Washer Operator	941-322-6828
South Fort Meade			
Plant/Field	Primary	IOC	813-500-6685
	Alternate 1	Flot Plant Operator	863-375-5258
South Pasture			
Plant	Primary	IOC	813-500-6685



Four Corners

Four Corners Landing Zone Coordinates:

	Location	Longitude	Latitude
1	Plant - East of Contractor Parking lot	82°5'06" W	27°38'44" N
2	Mine North Side – South of Field offices	82°8'50" W	27°39'10" N
3	Mine – CSS - West of the Central Screening station by area entrance	82°8'42" W	27°42'52" N
4	Mine South Side – Ona Compound	82°3'3" W	27°35'25" N
5	AgRock - West side of Fort Green Road - Northeast of AgRock Tower	81°57'26" W	27°41'08" N
6	South Pasture Plant: South office	81° 56'25" W	27° 35'17" N
7	South Pasture Admin: North Office	81° 56'53" W	27° 37'57" N

Four Corners Aerial Maps

Plant Building, Evacuation and Shelter in Place Map



Four Corners Aerial Maps, *continued*

North Compound Located on SR 39



Four Corners Aerial Maps, *continued*

Central Screening Station (CSS)



Four Corners Aerial Maps, *continued*

AgRock




South Side Ona Compound



South Fort Meade

South Fort Meade Landing Zone Coordinates:			
	Location	Longitude	Latitude
Plant	Front of East Training Room	81°45'32.92480" W	27°40'00.42683" N

Building, Evacuation and Shelter in Place Map



Building, Evacuation and Shelter in Place Map



Wingate

Wingate Landing Zone Coordinates:

	Location	Longitude	Latitude
Plant	North of Warehouse	82°07'41.8" W	27°30'22.6" N

Building, Evacuation and Shelter in Place Map



Field Evacuation and Shelter in Place Map

