



# Laboratory Safety Program

## Appendix A

### Laboratories in Mosaic Fertilizer LLC Operations

#### Covered by HAZCOM Program

##### **New Wales:**

Sulfuric Area - 01-02-03  
Sulfuric Area - Demins  
Sulfuric Area Area - 04-05  
Rock Area - Ball Mills  
PhosAcid Area - East/West Train  
PhosAcid Area - Third Train  
Clarification Area -Clarification  
ClarificationArea – Area 10  
DAP1 Area – DAP1  
MAP Area - MAP  
GMAP3 Area – GMAP3  
DAP2 Area - East/West  
AFI Area – AFI  
Multifos Area – Kilns  
Multifos Area – Mixed Feed

##### **South Pierce:**

Sulfuric Area - Sulfuric  
Sulfuric Area - Demin

##### **Riverview:**

Sulfuric Area – Sulfuric  
Dry Products - #5 plant  
Dry Products - #6 plant  
PhosAcid Area - PhosAcid  
Rock Area- Ball Mill

##### **Bartow:**

Sulfuric Area – Sulfuric #5/6 Plant  
Sulfuric Area – Sulfuric #4 Plant  
Dry Products - #4 DAP Plant  
Dry Products - #3 Dry Products Plant  
Phos Acid – Control Room Lab

#### Covered by Chemical Hygiene Plans

##### **Four Corners<sup>1</sup>:**

Quality Control Laboratory  
Metallurgical Laboratory

##### **New Wales**

Quality Control Laboratory  
Environmental Laboratory  
New Wales Pilot Plant

##### **Riverview**

Quality Control Laboratory

##### **Bartow**

Quality Control Laboratory

##### **South Fort Meade**

Quality Control Laboratory

##### **South Pierce**

Environmental Laboratory

<sup>1</sup> The Labs are located in one buildg and may be covered a single Plan.